
SHC. COPY

NOT A CONTROLLED

	E-E-I			COPY			0	2	
Г		60	革品			"			
	MODIFICATIONS NOUVELLE DEFINITION POUR REP. 03 ET 04 MODIFIER REP. 01 , REMPLACER REP. 20 ET 21 NOUVEAU REP. 22	CORRELATION A EFFECTUER AVEC OUTILLAGES EXISTANTS AVANT MISE EN SERVICE	APPEL A UN MODELE 3D THIS COPY IS GOOD FOR DAYS AFTER DATE OF ISS	108/03 TE:	22 1 DOUBLE 'COMBITIO' RECTIFIL VK7 21 1 VIS 'COMBITIO' RECTIFIL VK6 20 1 VKFB-MZ-68 STD YK6 19 1 ROMOBLLE PLATE MAU STD STD 18 1 VKS CHE MA-12 STD STD 17 2 VKS CHE MA-16 STD STD 16 2 PRET RAPPORTE MS LG.10 ThA 972706804 15 1 COMP-PARATEUR MITUTOYO REF. 1911		6 1 PALPERR 5 1 POIGNEE 4 1 MONS MOBLE 3 1 MONS FIXE 2 1 VIS, 1 1 CORPS	REP OUANT DESIGNATION MATIENE EC M. STEAM MATIENE EC M. G. DUPOUTS MITEMATIATION OF DESIGNATION	UT SANS SON AUTORISATION UT SANS SON AUTORISATION UT SANS SON AUTORISATION UT SANS SON AUTORISATION CONTROL OF THE CONTROL OF
	Φ								
				16	77		*		
			17:16:	181 051	OOLLE AU FREIN FILET FAIBLE	1151	22.	21 04	20, 03,
						Coupe A-A			



SHOP COPY

